

## 工事写真

A long, brightly lit hallway with a polished floor, white walls, and a series of white doors on the right side. The ceiling features exposed ductwork and lighting fixtures.A long, empty hallway with green walls and a grey carpet. The ceiling is exposed, showing pipes, conduits, and several bright lights. On the left wall, there are two doors and a light switch. On the right wall, there is a window. The hallway leads to a bright light at the far end.

京大(熊取)第二研究棟新営その他工事

工事写真

|     |                  |    |            |
|-----|------------------|----|------------|
|     |                  | No | 4          |
| 工 種 | ユニット工事           |    |            |
| 場 所 | 3階<br>トイレ        |    |            |
| 説 明 | 状況写真<br>トイレブース設置 |    |            |
|     |                  |    |            |
|     |                  |    |            |
|     |                  |    |            |
|     |                  |    |            |
|     |                  |    |            |
|     |                  |    |            |
|     |                  |    |            |
|     |                  |    |            |
|     | 撮影日              |    | 2023/12/26 |



|     |                  |    |            |
|-----|------------------|----|------------|
|     |                  | No | 5          |
| 工 種 | ユニット工事           |    |            |
| 場 所 | 3階<br>トイレ        |    |            |
| 説 明 | 状況写真<br>トイレブース設置 |    |            |
|     |                  |    |            |
|     |                  |    |            |
|     |                  |    |            |
|     |                  |    |            |
|     |                  |    |            |
|     |                  |    |            |
|     |                  |    |            |
|     |                  |    |            |
|     | 撮影日              |    | 2023/12/26 |



|     |                                |    |            |
|-----|--------------------------------|----|------------|
|     |                                | No | 6          |
| 工 種 | ユニット工事                         |    |            |
| 場 所 | 3階<br>アクティブラーニングスペース           |    |            |
| 説 明 | 状況写真<br>スライディングウォール<br>パネル吊り込み |    |            |
|     |                                |    |            |
|     |                                |    |            |
|     |                                |    |            |
|     |                                |    |            |
|     |                                |    |            |
|     |                                |    |            |
|     |                                |    |            |
|     |                                |    |            |
|     | 撮影日                            |    | 2023/12/26 |

